



City of North Richland Hills's
**Substandard Active
 Cases**
 Start date
 09/01/19 to 09/30/19

Short Address	Case Description	Case Start Date	Case Type	Last Completed Step	Last Inspection Date
6509 Wakefield Rd.	Rotted/damaged wood throughout the structure	09/10/2019	Substandard	Mail Minimum Standards Notice	09/26/2019
6813 Parkwood Dr.	Damage deck in rear yard	09/12/2019	Substandard	Mail Minimum Standards Notice	09/12/2019
7913 Birchwood Dr.	Gutter falling down.	09/19/2019	Substandard	Mail Minimum Standards Notice	09/19/2019
6836 Glenhurst Dr.	Shed in rear yard has a huge hole on the back side of it	09/19/2019	Substandard	Mail Minimum Standards Notice	09/19/2019
6341 Dorchester Trl.	Broken front window pane	09/19/2019	Substandard	Mail Minimum Standards Notice	09/20/2019
7201 Janetta Dr.		09/20/2019	Substandard	Mail Minimum Standards Notice	09/20/2019
4916 Eldorado Dr.	Foundation needs repair, broken windows, HVAC unit is not operational, water heater is not operational, illegal gas heaters in bathrooms, exterior soffits missing screens.	09/23/2019	Substandard	Mail Minimum Standards Notice	09/23/2019
6321 Yarmouth Ave.	Broken front window	09/24/2019	Substandard	Mail Minimum Standards Notice	09/24/2019
7216 Edinburg Dr.	Damage siding bricks on ground & meter base pulling from the service box	09/24/2019	Substandard	Mail Minimum Standards Notice	09/27/2019
7625 Teresa Ct.	Brick remove from exterior wall in rear of property a repair was made to jet tub inside house per occupant.	09/24/2019	Substandard	Mail Minimum Standards Notice	09/24/2019

TOTALS:	Total Cases:	10
----------------	--------------	-----------